Appl. No. 10/604,789 Amdt. dated May 12, 2005 Reply to Office action of April 07, 2005

Amendments to the Specification:

25

Please replace Paragraph [0020] with the following amended paragraph:

The electronic apparatus 10 is a very complicated product, any problem of any part may interrupt the operation of the electronic apparatus 10. Faulty operation can be due to any of a variety of reasons, including hardware or software problems, or even because the fan 22 or a bus line inadvertently becomes loose. Therefore, when problems of the electronic apparatus 10 occur, since the holes 15 on the first side wall 24 correspond to the motherboard 14 on the second side wall 14, the user can look inside the electronic apparatus 10 through the holes 15. For instance, if the electronic apparatus 10 is down, 10 the user can know the condition of the fan 22 or the bus line by looking inside through the holes 15 on the housing 12. Only when the fan 22 stops or the bus line is loosened, the user should shut down the electronic apparatus 10 and remove the housing 12 for further repairing. If no visible hardware problems have occurred, the problem may be in software so that time is not wasted opening the housing 12. Additionally, the transparent 15 dust-proof member 16 is installed inside or outside the first side wall 24 of the housing 12. The transparent dust-proof member 16 may be installed either against the holes 15 separated from the holes by a predetermined distance by adhering to the housing 12, ormay be separated from the housing 12. The transparent dust-proof member 16 is made of glass or plastic to prevent dust from entering into the electronic apparatus 10 and 20 interrupting its operation.

Please replace Paragraph [0022] with the following amended paragraph:

Please refer to Fig.4 showing a perspective view of an electronic apparatus 50 according to a third embodiment of the present invention. The devices of the electronic apparatus 50 in Fig.4 having the same numberings have the same name and function as those of the electronic apparatus 10 in Fig.1, so that a further description is hereby omitted. The difference between the electronic apparatus 50 and the electronic apparatus 10 is that, the

Appl. No. 10/604,789 Amdt. dated May 12, 2005 Reply to Office action of April 07, 2005

electronic apparatus 50 includes a housing 52, a motherboard 14 may be installed on a second side wall 58, a first side wall 56 includes a plurality of holes 55, but a transparent dust-proof member 54 is installed in the holes 55. The transparent dust-proof member 54 is made of glass or plastic, which can be inserted in the holes 55 adhering to the housing or being separated from separated from the holes 55 by a predetermined distance by adhering to the housing 52.